MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hopkins University Baltimore, Maryland 21218 (301) 235-0771

COUNTIES (MD/PA)	BALTIMORE/YORK
M&D milestone no.	47 (50)
MHT-HSI no. MHT MAGI no.	BA-1566
MHT MAGI no.	
RROTECTED ENDA	NGERED/MIRRING

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5'quadrangle UTM 18.35638.439792 New Freedom bench mark/date none original site/WWW/date 1766 N/S Orwig Rd R/W. Maryland Line, MD vicinity. About 0.9 mile due W of York Rd. on unsurfaced shoulder of narrow blacktop (Baltimore) County rd grade level, in area changing from open farmed fields to residential development (both sides of rd). Marker easily seen from rd all seasons, now with metal hazard post on E/S. DIRECTIONS TO SITE:

From M&D 46 (49): follow York Rd SE 0.2 mile to recently reworked Freeland Rd (Rte. 409); turn right (W) & follow 0.6 mile to intersection of Heathcote Rd; turn right (N) & follow 0.2 mile to Y-junction of Orwig Rd; bear left (NW) on Orwig (over) DESCRIPTION/MEASUREMENTS: original/replika/replacement/date 1766; squared oolitic DESCRIPTION/MEASUREMENTS: original/replica/replacement/date 1706; squared collications post, standing about I' above ground; P on N/S, M on S/S
N face (PA): ll%" wide x 13" high; P clear; trace of circle panel, fluting & bits of margin remain; chips all edges & corners
E face: l2%" wide x ll%" high; most fluting, no margins remain; chips all edges & corners
S face (MD): ll%" wide x ll" high; M clear; trace of circle panel, no fluting or margins remain; badly chipped face, edges & corners
W face: l2%" wide x l2%" high; some fluting, no margins remain; chips all

edges & corners
patches of planes & fluting discernible; surfaces badly chipped & top:

none indicated on maps; none observed

1900-03 Resurvey notes (order no.50), as in MGS Vol. 7, 1908, p. 86

50. Milestone No. 47, M. & D., 1766, in an open field and close to a short section of the road closely following the boundary, about a mile west of the pike.

1950 Inspection notes (present order no.48, photo no.47) as in Bayliff, 1959, Appendix C, p. 99

50. Original monument, being exposed to machinery, is chipped on south side. Firm foundation.

1979-80 Inspection notes: order no. 47 (50); photos/negatives/slides no. 47 (50) 47 (50). Original M&D monument of 1766 in place, in fair condition, firmly set; letters clear but chips all edges, corners & south face. Endangered by site.

SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones

tax map 3 , block , P. , deed / , acres Baltimore County, Department of Public Works, County Office Building, Towson,

MD 21204 (Orwig Road right-of-way) tax map A-J block , PLR5 , deed 55-P /410 , acres 13 Russell W. Cunningham, Jr. & Denelda D., RD 1, New Freedom, PA 17349 Phone: (717) 235-2321

RECORDED BY: names, addresses, phones, dates Alice Martin 3/9/79, 12/5/79, 1/19/80 14308 Mount Ave., Phoenix, MD 21131 Phone: (301) 472-2128 Assisted by Clyde E. Martin

Also see: reverse side X , B&W photos X , negatives X , color slides X , maps X , MHT-HSI form , other X

DIRECTIONS TO SITE, continued

0.6 mile to marker. Pull off on road shoulder at nearby level stretch. Marker is about 1' from edge of pavement. Handsome small stone dwelling (old farmhouse) nearby to north. No crossing of private property. No permission necessary.

NOTES.

According to Maryland tax maps and the Baltimore County Bureau of Highways Seventh District shop superintendent, Mr. Klingelhofer (phone 357-5628) and engineer Mr. Gill (phone 494-3700): this monument stands within the Orwig Road R/W (presently 33') and is/maintained by Baltimore County. Because of repeated scrapes not only by the farm machinery (on N/S) but road maintenance machinery, Baltimore County erected the metal hazard post (on E/S of stone). Property on both sides of this road is now subdivided and new houses/burlt. With increasing development and traffic, the monument will need some concerted protection. I have talked with people at the DPW, who will take the marker into consideration if and when Orwig Road improvements are made (i.e. widening slightly to south, 2's provided by developer R/W).

I recommend MGS contact with DPW and superintendent to/reinforce concern about preservation of this stone.

B&W PHOTOS/NEGATIVES

5x7	NE corner (neg # 1980.2.6),	Alice Martin	1/19/80
5x7	SW corner (neg # 1980.2.4),	11	11
31/2×5	View SE (neg # 1980.2.8),	11	11
3½x5	View NE (neg # 1979.3.2)	11	3/9/79
31/2×5	View W (neg # 1979.3.14)	11	11

COLOR SLIDES


			Alice Martin	1/19/80		
2x2	SW corner	(1980.1.2)	11	11		
2x2	View NE of	f stone & se	tting (1980.1	.1). Alice	Martin	1/19/80


MAPS

USGS 7½' topographic quadrangle section 1900-03 Resurvey engineer's map (Plate XX), updated MD tax map section

OTHER

2 B&W duplicate contact photos (c. 1948-50), 3/4x5, gift to MGS by Maryland Historical Society (Prints & Photographs Dept.) deaccessioned 9/23/81 from the Trussell Collection PP2.40.1 (N/S), PP2.40.2 (S/S)








HED WEST LINE: HILLSTONE 47 (50)
LOCKING NE

PHOTO: ALICE MARTIN 3/9/79 (1979.32)



MAT-NSI: BA-ITI-NEW-1566

MASON EDIXON WEST LINE ?
MILESTONE NO. 47, LOCKING
SE ACROSS ORWIG RE. TO NEW
DUBIT HOUSE E RESIDENTIAL
DEVOPMENT LAND

(1980.2.8)



PROBLEM TO HIS FRENCHES: TRUSTER CALL PROJECTION 2.

135



HER EINT : FRINT HAS TRUTELL COLLS PROMED !!

HEREN LEVEL NEST LIVE: MILESTREE 119 (SE)

AND

PHOTE: DIE 21 TRUSPIL C. 1948-60 (ARMARIA)

135




MOS

MUSIN 2 DIVON WEST LINE I THESTONE HT (50)

NE CORNER (-10)

PHOTO: ALICE MARTIN 1/19/80 (1880-2.6)



BA-1566 HASON & DIXON WEST LINE ! MILESTONE UT (50) PHOTO: ALICE HARTIN 1/19/80 (1085-2-4)



MOS

MED WEST LINE: MILESTONE 47 (50)

VIEW OVE W OF STONE, READ EHAZARD

MARKER

PHOTO: ALKE MARTIN 3/9/79 (1979.3.14)